



							
H1106	0,15	10X100	115	22,2			
H1107	0,20	10X100	125	22,2			
H1108	0,45	5X50	180	22,2			
H1108E	0,55	5/50	180	25,4			
H1109	0,63	5X50	230	22,2			
H1110	0,3	5X50	150	22,2			
H1111E	0,9	5X50	250	25,4			